

Permits & Inspections Division 52 W College Ave. San Angelo, TX 76903 (325) 657-4210, #1 www.cosatx.us

FRVIT

INSPECTIONS NEEDED ON RESIDENTIAL CONSTRUCTION (Listed in order of completion)

Plumbing rough-in

Building Foundation

Building Framing

Electrical rough-in

Mechanical rough-in

Plumbing top-out

Interior Firewall (if applicable)

Building Insulation

Building fireplace (if applicable)

Plumbing water, sewer, gas

Plumbing Final

Electrical Final

Mechanical Final

Building Final